



### Installation:

Push and hold the fixture into the installation hole. Tighten the 2 screws until the fixture sits firmly in place.

### Connections:

Connect black wire (live) to colored wire, white (neutral) to white and bare copper (ground) to bare copper wire from fixture. The use of a wire clip (not included) is recommended. Installation must be in conformance with the electrical code of your region.

REQUIRED BULB:  
(NOT INCLUDED)

MR16



50W  
MAX

INSTALLATION HOLE:

3 7/8" DIA.

### WARNING

SHUT OFF POWER TO SERVICE LEADS BEFORE  
PROCEEDING WITH CONNECTIONS

